















**Excavation** 

**Civil Works** 

Building Top-off Start of Glass Installation Building Water Tightness

**Tested MEFP** 

Building Completion and Turnover



### **ON-GOING WORKS**

#### **Excavation Works**

Excavation completed.

### **Civil/Structural/Architectural**

 Ongoing rebar installation on columns (2nd lift)

#### **Mechanical Works**

Ongoing stair pressurization duct at fire exit.

#### **Electrical Works**

 Ongoing installation of roughing-ins and lighting layout.

### **Plumbing/Sanitary**

 Installation of perforated pipes for Basement 4 to 1

#### **Fire Protection**

Ongoing installation of roughing-ins.

















Excavation

**Civil Works** 

Building Top-off Start of Glass Installation Building Water Tightness

**Tested MEFP** 

Building Completion and Turnover

# **PROGRESS PHOTOS**









**Basement 1 parking level** 

















Excavation

**Civil Works** 

Building Top-off Start of Glass Installation

Building Water Tightness

**Tested MEFP** 

Building Completion and Turnover

# **PROGRESS PHOTOS**









**Ground floor level area 2**